


CNC software is now available for use with Acorn, AcornSix, Hickory, Allin1DC, Oak and MPU11. Please [Follow the installation instructions](#). Do not use "restore report" using a report from an earlier version.

Download CNC12 v5.24 here.

https://www.centroidcnc.com/centroid_diy/centroid_cnc_software_downloads.html


This is a free CNC software update! All previous license files file work with this new version of CNC12 software (in their respective categories: Acorn mill licenses work with Acorn mill, Oak lathe licenses work with Oak lathe CNC12, etc.)

1. Updated Mill and Router F7 Auto Zero Part Setup menu with improvements.



F7 Auto Z zero will now trigger off any type of Probe Input definition. Useful for using a TT to set Part Z zeros. Either the Probe or the TT or Touch Plate can be used with F7 Auto Z zero menu.

Notes: If you have the TT set to subtract the TT height for tool length measurements, F7 Auto Zero will also subtract the height of the TT therefore setting the Z zero location on top of whatever the TT is sitting on.



And same for a Touch Plate.

347 Reset Cleared
490 Reset Initiated. Press Reset to Clear

Auto Z Zero

*** Choose which Touch Device to use! ***

Press 1 = Seek the TOOL TOUCH OFF
- or -
Press 4 = Seek the TOUCH PROBE
- or -
Press 8 = Seek the TOUCH PLATE

CEL to cancel

Approach from
Center
Center

Help: Shift F12

Manual F1	Laser F2	Probe F3	Plate F4	CSR F5	Auto Zero F7	Set XY F8	WCS CSR Table F9	Set F10
--------------	-------------	-------------	-------------	-----------	-----------------	--------------	---------------------	------------

The new Auto Part Z zero macro also employs the new P0 probing cycle command argument which tells the probing cycle to trigger off of any input setup as a probe. So, for instance when probing a TT with a Touch Probe the probing cycle will use whatever input triggers first.

Note: You can always type in the TT height value here as well if you don't have CNC12 set to subtract the TT height for Tool measurement or if you desire to set the z zero at another position.


Set Part Zero Position

Axis	Part Position	Edge Finder Dia.	Approach from
X	0.000	0.000	Center
Y	0.000	0.000	Center
Z	45.000	Tool #: 8	

Help: Shift F12

In this example above the TT height is 45 mm, which sets the part zero at the bottom of the TT with "subtract TT height" set to No in the Wizard.

2. Improvements made to the Tool Library Auto Tool Height Measurement Macro.
 C:\cncm\system\tool_offset_auto_measure.cnc



The Auto Tool Height Measurement macro (tool_offset_auto_measure.cnc) will auto recognize all configured touch devices and present the operator with a choice of touch devices to use during the tool height offset measurement cycle.

The new Auto Tool Height Measurement macro employs the new P0 probing cycle command argument which tells the probing cycle to trigger off of any touch device input. So, for instance when measuring a Touch Probes Tool Height Offset with a TT, the probing cycle will use whatever input triggers first either the TP or TT.

Just like all Centroid provided macros, the tool_offset_auto_measure.cnc macro is user editable so users may edit to their particular application and work flow.

Note: You can also hold the SHIFT key in the Tool Offset menu to make use of the old (previous to v5.24) F3 Auto Measure hard coded auto tool measure routine

3. Added: PWM Laser Delay Fine Tuning Parameter 424 added. Useful for compensating for millisecond delays introduced when using RAS with Clearpath servos.
4. Added new M-codes: M297 (Defeat Soft Travel Limits) and M298 (Re-enable Soft Travel Limits). The default state of the software behaves as if M298 has been called. M297 can either be called during a job or in MDI mode to temporarily defeat the soft travel limits. This lasts until:
 - M298 is called
 - MDI mode is exited
 - The job finishes (or is canceled/aborted)

Note that if M298 is used within a job, soft travel limits will be treated as active again for any subsequent moves (or until M297 is called again).

Useful for commanding special machine movements OUTSIDE the Software Travel Limits. Use with caution!

Added M297 to Wizard generated Home Programs.

5. Added M291 - Reset MPG Offset. Ultimate License required.

M291 resets any accumulated MPG offset for all axes across all MPGs, provided that PLC program "SV_MPG_X_OFFSET_MODE" (where X represents the MPG number) is active.

Example (assuming an accumulated 0.25" offset on the Z-axis):

Without M291:

G0 Z0 ; Though Z0 was commanded, the Z-axis will move to an offset position from Z0 - in this case, 0.25"

With M291:

M291 ; reset MPG offsets

G0 Z0 ; Z-axis moves to Z0 as commanded now that the MPG offset has been reset

Note: Custom PLC program interaction is needed for this feature as the PLC program is in direct control of MPG modes.

Useful for when using an MPG wheel to adjust the position of an axis on the Fly. In special CNC applications the operator can adjust the position of an axis under CNC program control using the MPG while the job is running and when the job is finished CNC12 can be commanded to cancel any offset amount that the operator added or subtracted from that axis with the MPG OR leave the offset applied.

6. Fixed bug where M115/116 P0 would not register a NO (normally open) probe without a detect tripping
7. Fixed bug with M115/116 P0 where a NC probe without a detect in combination with any other device would result in all device inputs being ignored if probe protection via tool number was not active
8. Fixed bug where user defined message would be discarded if M0 jogging was not enabled for M200/201
9. Fixed bug where M223 would power an axis motor after an M93 call for that axis
10. Fixed bug where running a job from the Run-Search menu and then reentering the menu later would result in CNC12 crashing
11. Added Centroid API call `Axis.GetPower(...)` to get the power status of a given axis.
12. Removed the on screen ESC key from the RTG screen.
13. Fixed 'bug' where fkeys would disappear not showing anything when a keyboard modifier is pressed. This occurred because CNC12 attempted to draw alternative keys but found none.
14. Removed excess space on the run time graphics screen to allow 5+ axes to fit better

15. Added option to ignore all limit switch inputs or not when homing for Acorn.

When using Limit Switches in conjunction with Home Switches

Ignore all Limit Switch Inputs when Homing? No

"No" is the default and recommended setting
"Yes" is for special applications such as when dedicated limits are used to "protect home switches"


When set to "Yes" any limit switch input triggered while homing will be ignored. Use this feature with caution. This feature is typically used when "protecting" home switches with limit switches. (limits trip first) which allows the seeking of the home switch to continue right past a limit switch.

When using Limit Switches in conjunction with Home Switches

Ignore all Limit Switch Inputs when Homing? Yes

"No" is the default and recommended setting
"Yes" is for special applications such as when dedicated limits are used to "protect home switches"

For instance NO prox limit switches wired into Input 6 in parallel and Metrol precision micro switches ran in series with Input 6



Would produce a home program like this by the Wizard.

```
;Perform Homing commands  
;Disable any assigned limit switch inputs  
M94 /105 ; disable Limit All  
M92/Z L1  
M26/Z  
M92/Y L1  
M26/Y  
M91/X L1  
M26/X
```

```
;Enable all limits  
M95 /101 /102 /103 /104 /105
```

Then you would hand edit it to reset home within the travel of the limits protecting the home switches so the software travel limits would stop the machine from hitting the limits as well.

```
;Perform Homing commands  
;Disable any assigned limit switch inputs  
M94 /105 ;disable LimitAll  
M92/Z L1  
M26/Z  
M92/Y L1  
M26/Y  
M91/X L1  
M26/X  
G91 X1.000Y-1.000Z-.5000  
M26/X/Y/Z
```

```
;Enable all limits  
M95 /101 /102 /103 /104 /105
```

Note: This feature will be disabled (grey'd out) if any "homelimit" inputs are set. Since by definition these inputs act as both a home and a limit switch input.

When using Limit Switches in conjunction with Home Switches

Ignore all Limit Switch Inputs when Homing?

 No

The "Ignore all Limit Switch Inputs" feature not available for use with any "HomeLimit" input definition.

FirstAxisHomeLimitOk
SecondAxisHomeLimitOk
ThirdAxisHomeLimitOk
FourthAxisHomeLimitOk
HomeLimitAll

By definition these individual inputs perform the duty of both a home switch and a limit switch so CNC12 can't ignore them.

Remove any "HomeLimit" input from the Input Definition table to use the "Ignore all Limit Switch

16. Added Centroid API calls `WCS.SetWorkpieceLocation(...)` to set wcs at a location other than zero and `Job.SetSystemVariable(...)` to set a system variable. Added some additional validation to preexisting WCS calls
17. Removed P228 (S Curve) from the ad2 presets menu as it is a deprecated experimental feature.
18. Edited the Default Router smoothing profiles "V-Carve" and "3-D Relief Fine" to have a S Curve value of zero
19. Added `ERROR_LICENSE_LOCKED` error code to Centroid API return codes for features locked behind a pro or ultimate license
20. Added PLC IO to the Report Summary
21. Fixed bug where Centroid API call `SetWorkpieceOrigin` was not working
22. Fixed bug where tool check with an unplugged NC probe would result in a probe tripped error
23. Fixed bug where swing-arm ATCs wouldn't initialize
24. Increased upper constraint of P40 for Metric to 0.0254
25. Fixed PWM2 output for AcornSix that was broken under certain combinations and made it more robust at the same time. Now AcornSix PWM2 will only turn on with the M37 (laser on) Note: The Laser feature G37 (Laser power based on velocity, aka velocity modulation) only works with PWM2 not PWM1, (think of it this way: PWM1 is for spindles, PWM2 is for Lasers)
26. The Simple PLC diagnostic menu can be launched from more (but not all) menus in CNC12
27. Fixed bug where the WCS Config menu would display incorrect function keys if a keyboard modifier was pressed
28. Upon completion of a job, the g-code display will return to the top of the file
29. Fixed bug where g-code display would require a job to be run at least once before canceling the job and displaying the last known g-code line correctly
30. Improvement: Allow non zero software travel limit when used in conjunction with screw comp.
31. Fixed a bug with Wizard related to P423 where it would let larger values than valid numbers which are: 0-255

32. Reinstated the v4.82 color schema for g-code display while running a job which was accidentally ignored when the Color Picker was introduced.

```
11. N11 M03 S5000 F15.0
12. N12 G4 P2.0
13. N13 G43 G0 Z0.05 H1
14. N14 G01 Z-0.0035 F13.5
15. N15 ; FALCONS LOGO
16. N16 G01 X8.9569 Y0. F15.0
17. N17 G01 X8.9569 Y9.9998
18. N18 G01 X0. Y9.9998
19. N19 G01 X0. Y0.
20. N20 G00 Z0.05
21. N21 G00 X3.8586 Y2.3516
```

33. Acorn/AcornSix/Hickory Wizard: add M297 to wizard generated and default home files

34. Acorn/AcornSix/Hickory Wizard Improvement to ATC Rack Mount logic made to be more flexible: M95/80 will turn off ToolRack In, M95/81 will turn off ToolRack Out

35. Plasma: M64 marking macro: Fixed undefined variable.

36. Improved the input output text report in the report.txt for better human readability.

37. Added a “maximum scale difference error” parameter for each axis. CNC12 uses this value to determine when to issue an error message. Users can now specify the maximum allowable scale to actual position error allowed before CNC12 issues a 410 fault message. P571 thru 578 571 = axis 1, 572 = axis 2, 573 = axis 3 etc.. these values are ‘echo’d” in the CNC12 scale setup menu.

Axis	Label	Input	Enabled	Scale Counts/Inch	Ratio	Deadband	Velocity	Max Diff (in)
1	Z	0	N	0.0000	0.0000	0	0.0000	0.0100
2	X	2	Y	50800.0000	0.8192	1000	0.0700	0.0200
3	C	0	N	0.0000	0.0000	0	0.0000	0.0002
4	M	0	N	0.0000	0.0000	0	0.0000	0.1000
5	N	0	N	0.0000	0.0000	0	0.0000	0.1000
6	N	0	N	0.0000	0.0000	0	0.0000	0.1000
7	N	0	N	0.0000	0.0000	0	0.0000	0.1000
8	N	0	N	0.0000	0.0000	0	0.0000	0.1000

Save
F10

506	0.0000	526	0.0000	546	2.5000	566	0.0000	58
507	0.0000	527	0.0000	547	0.0500	567	0.0000	58
508	4.0000	528	0.0000	548	10.0000	568	0.0000	58
509	0.0000	529	0.0000	549	5.0000	569	0.0000	58
510	0.0000	530	0.0000	550	0.0000	570	0.0000	59
511	0.0000	531	0.0000	551	0.0000	571	0.0100	59
512	0.0000	532	0.0000	552	0.0000	572	0.0200	59
513	0.0000	533	0.0000	553	0.0000	573	0.0002	59
514	0.0000	534	0.0000	554	0.0000	574	0.1000	59
515	0.0000	535	0.0000	555	0.0000	575	0.1000	59
516	0.0000	536	0.0000	556	0.0000	576	0.1000	59
517	0.0000	537	0.0000	557	0.0000	577	0.1000	59
518	0.0000	538	0.0000	558	0.0000	578	0.1000	59
519	0.0000	539	0.0000	559	0.0000	579	0.0000	59

Axis 1 Maximum Scale Difference (in, mm, or deg)